

Governor GREG BELL Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER

Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA Division Director

Representatives Present During the Inspection:			
OGM	Priscilla Burton		
Company	Dave Shaver		

Inspection Report

Permit Number:	C0150032		
Inspection Type:	PARTIAL		
Inspection Date:	Thursday, October 20, 2011		
Start Date/Time:	10/20/2011 10:00:00 AM		
End Date/Time:	10/31/2011 2:00:00 PM		
Last Inspection:	Tuesday, October 11, 2011		

Inspector: Priscilla Burton,

Weather: sunshine turning to overcast and snow flurries

InspectionID Report Number: 2905

Types of Operations

Reprocessing

Accepted by: jhelfric 11/1/2011

Permitee: GENWAL RESOURCES INC Operator: GENWAL RESOURCES INC Site: CRANDALL CANYON MINE

Address: PO BOX 910, EAST CARBON UT 84520-0910

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Cu	FFE	nt	Ac	rea	ges

80 Total Permitte	6,235.80
15 Total Disturbe	27.15
Phase I	
Phase II	
Phase III	

Mineral Ownership

✓ Federal ✓ Underground State Surface County Loadout Fee Processing Other

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The site has dried out from previous rains and SCAMP returned to the site on October 20, 2011. By Tuesday October 25 the SITLA road was reclaimed to within 700 ft. of the USFS boundary. Wood straw had been spread to the point of the ridge, approximately 1,000 feet west. No seed has been spread yet. More laborers are needed to complete this job before the weather shuts it down. Refer to photos in the Images folder taken in October 2011.

Inspector's Signature:

Priscilla Burton.

Date

Saturday, Octo



Inspector ID Number: 37

Permit Number: C0150032 Inspection Type: PARTIAL

Inspection Date: Thursday, October 20, 2011

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers				
3.	Topsoil				
4.a	Hydrologic Balance: Diversions				
4.b	Hydrologic Balance: Sediment Ponds and Impoundments				
4.c	Hydrologic Balance: Other Sediment Control Measures	~		~	
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste				
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading	~		✓	
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.2	Roads: Construction, Maintenance, Surfacing				
16.b	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance			i	
22.	Other				

Permit Number: C0150032 Inspection Type: PARTIAL

Inspection Date: Thursday, October 20, 2011

Page 3 of 3

4.c Hydrologic Balance: Other Sediment Control Measures

I recommended that the six remaining (new) excelsior logs be installed at the location of the former French drain along the SITLA road, because the reclaimed slope is steep in this location and it meets an equally steep undisturbed slope with no concave area or vegetation to slow flow.

12. Backfilling And Grading

Chase Webster, SCAMP hoe operator worked Oct 20 through Saturday Oct. 22 and Monday Oct 24. At midday on Tuesday, October 25, the SITLA road was reclaimed to approximately 700 ft from the USFS boundary.